

P-1 Subterranean Level Garage Defects

Defect

- 1 Leakage stain @ structural floor slab to wall @ PS 70A (See photo # 343 - 345)
- 2 Leakage from @ wall / concrete soffit @ PS 70 (See photo # 418 - 420)
- 3 Leakage from cracks @ ceiling & wall areas in NW Mechanical Room (See photo # 410 - 416)
- 4 Overhead Leak below Museum Construction (See photo # 421 - 422) Leaks noted 3/22/07
- 5 Ceiling cracks & leaks in Electrical Room (See photo # 423 - 425)
- 6 Cracks / efflorescence @ structural slab & ceiling - PS 36M (See photo # 336 - 339)
- 7 Rain water leaking thru slab - Museum construction incomplete (Below Museum) (See photo # 340 - 342) Leaks noted 3/21/07
XX

P-2 Subterranean Level Garage Defects

Defect

- 8 Coating delamination in drive aisle near PS 132 (See photo # 59 - 60)
- 9 Ramp water stained at wall (See photo # 426 - 428)
- 10 Leakage / stains on structural slab at ceiling - PS 145 (See photo # 366 - 372) **Area of prior repairs**
- 11 Leakage at stair 3 from Parking level 2 to Parking level 3 (See photo # 331 - 335)
- 12 Leakage and stains @ PS 169 (See photo # 358 - 359)
- 13 Leakage and stains @ PS 189 (See photo # 353 - 357)
- 14 Leakage and stains at structural slab to foundation wall @ PS 209 (See photo # 351 - 352)

P - 2 Subterranean Level Garage

Defect

- 15 Driveway coating damaged / delaminated / HL crack @ PS 132 (See photo # 59 - 60)
- 16 Driveway stains @ PS 174 (See photo # 61) **Previous repairs**
- 17 Structural slab ceiling crack / stain / efflorescence (See photo # 62)
- 18 Leak & stains @ crack @ ceiling & structural slab - PS 195 (See photo # 429 - 431)

P - 2 Additional Leak Locations

- 19 Construction Joint @ PS 152 NO PHOTO - SEE LEAK SURVEY MAP
- 20 Construction Joint @ PS 156 NO PHOTO - SEE LEAK SURVEY MAP
- 21 Wall leak @ PS 160 NO PHOTO - SEE LEAK SURVEY MAP
- 22 Construction Joint @ PS 167 NO PHOTO - SEE LEAK SURVEY MAP
- 23 Wall leak @ PS 164 NO PHOTO - SEE LEAK SURVEY MAP
- 24 Wall leak @ PS 175 NO PHOTO - SEE LEAK SURVEY MAP
- 25 Wall leak @ PS 176 NO PHOTO - SEE LEAK SURVEY MAP
- 26 Wall leak @ PS 177 NO PHOTO - SEE LEAK SURVEY MAP
- 27 Wall leak @ PS 181 NO PHOTO - SEE LEAK SURVEY MAP
- 28 Wall leaks @ PS 191 NO PHOTO - SEE LEAK SURVEY MAP
- 29 Wall leak @ PS 203 NO PHOTO - SEE LEAK SURVEY MAP

P-2 Subterranean Level Garage

Additional Leak Locations

Defect

30 Wall leaks @ PS 205.....	NO PHOTO - SEE LEAK SURVEY MAP
31 Wall leaks @ PS 154.....	NO PHOTO - SEE LEAK SURVEY MAP
32 Wall leaks @ PS 158.....	NO PHOTO - SEE LEAK SURVEY MAP
33 Wall leaks @ PS 172.....	NO PHOTO - SEE LEAK SURVEY MAP
XX	

P - 3 Subterranean Garage Level Defects

- 34 Floor and ceiling leaks in NE Storage Locker Room (See photo # 437 - 445)
- 35 Leak / stain / wall crack & efflorescence at PS 331 (See photo # 20 - 23)
- 36 Wall cracks / stains @ PS 339 (See photo # 26 - 29) **Area of previous repairs**
- 37 Wall crack / stains @ PS 343 (See photo # 30 - 31)
- 38 Slab on grade coating damage / coating delamination / Active water leak @ PS 352 - 354 (See photo # 32 - 33) **Prior repairs**
- 39 Foundation wall crack extends across driveway SOG thru PS 353 / PS 509 (See photo # 34 - 39) **Prior Repairs**
- 40 Water stain from hose bib @ PS 357 (See photo # 40 - 41)
- 41 SOG coating damage @ PS 355 (See photo # 42) **Previous Repairs**
- 42 Foundation wall leak / stains @ PS 367 (See photo # 43 - 47) **Previous Repairs**

P-3 Subterranean Level Garage

<u>Defect</u>	<u>Previous Repairs</u>
43 <u>Driveway SOG coating repairs @ PS 370 (See photo # 48)</u>	
44 <u>SOG damage diagonally across drive aisle from PS 407 to PS 463 (See photo # 49 - 54)</u>	<u>Area of previous repairs</u>
45 <u>SOG Coating damaged @ PS 458 & PS 459 (See photo # 55)</u>	<u>Area of previous repairs</u>
46 <u>SOG Coating damaged @ PS 447 (See photo # 56)</u>	<u>Area of previous repairs</u>
47 <u>Foundation wall crack @ PS 434 (See photo # 57 - 58)</u>	
48 <u>Water stains & active leak @ slab to wall up 27" in PS 440 - 442 (See photo # 245 - 246)</u>	
49 <u>Wall Leak & stains @ PS 440 (See photo # 247 - 249)</u>	<u>Area of prior repairs</u>
50 <u>Crack / stain @ control joint to slab @ PS 438 (See photo # 250 - 251)</u>	
51 <u>Wall crack / leak & stains @ PS 434 (See photo # 252)</u>	
52 <u>Stains & leaks @ wall cracks in PS 432 (See photo # 253)</u>	
53 <u>Stains & coating damage / slab wet in driveway @ PS 449 (See photo # 254 - 255)</u>	<u>Area of prior repairs</u>
54 <u>Driveway stains / leaks @ PS 458 (See photo # 256 - 259)</u>	<u>Area of prior repairs - Injection ports left in place</u>
55 <u>Drive aisle stained & wet from PS 407 to 458 (See photo # 260 - 263)</u>	<u>Area of prior injection repairs</u>
56 <u>Wall cracks leak / staining continuing onto slab @ PS 418 - 416 (See photo # 264 - 265)</u>	
57 <u>Injection ports left in place @ storm drain @ PS 415 (See photo # 266 - 267)</u>	
58 <u>Leak & heavy stains @ slab to wall transition - PS 413 (See photo # 268)</u>	

P-3 Subterranean Level Garage

Defect

- 59 Leakage / heavy stains @ slab to wall transition - wall wet & peeling - PS 398 - 400 (See photo # 269 - 271)
- 60 Leak / stain @ slab coating - PS 466 - 468 (See photo # 272 - 273) **Area of prior repair**
- 61 Leak / stain from SOG to 2nd level structural slab @ PS 371 - 369 (See photo # 274 - 278) **Area of prior repairs**
- 62 Wall crack leaks / stained @ PS 367 (See photo # 279 - 281) **Area of prior wall repair**
- 63 Leak at control joint @ PS 365 (See photo # 282)
- 64 Leak / stains full wall height @ PS 361 (See photo # 283 - 285) **Area of prior repairs**
- 65 Leakage stain at SOG to column @ PS 359 - 360 (See photo # 286 - 287)
- 66 Coating delaminated at drain @ PS 499 - 501 (See photo # 288)
- 67 SOG Coating delamination / stains diagonally to PS 355 (See photo # 289 - 292) **Prior repairs / injection ports left in place**
- 68 Coating delaminated at driveway drain @ PS 354 - 355 (See photo # 293)
- 69 Injection port devices left in place @ SOG & storm drain - PS 354 (See photo # 294 - 295)
- 70 SOG stained & wet @ PS 352 - 353 (See photo # 296 - 302) **Area of prior repairs**
- 71 SOG cracked & stained @ PS 509 - 510 (See photo # 303 - 305) **Area of prior repairs**
- 72 SOG coating delaminated / wet @ PS 352 (See photo # 328 - 330) **Area of prior repairs**
- 73 Wall leak & stains from level 2 to level 3 in stairwell @ PS 361 (See photo # 331 - 335)
- 74 Control joint leaks / stained @ PS 331 (See photo # 24 - 25)

P-3 Subterranean Level Garage

Defect

- 75 Leak / stain in rear corner of Storage unit - NO ACCESS - (See photo # 432 - 433) Previous repairs
- 76 Leaks / wet stains in Storage unit (See photo # 434 - 436) Previous repairs

P-3 Subterranean Level Garage

Additional Leak Locations

Defect

- 77 Construction Joint leak @ PS 329 NO PHOTO - SEE LEAK SURVEY MAP
- 78 Wall leak @ PS 339 NO PHOTO - SEE LEAK SURVEY MAP
- 79 Wall leak @ PS 341 NO PHOTO - SEE LEAK SURVEY MAP
- 80 Wall leak @ PS 343 NO PHOTO - SEE LEAK SURVEY MAP
- 81 Wall leak @ PS 345 NO PHOTO - SEE LEAK SURVEY MAP
- 82 Construction Joint leak @ PS 347 NO PHOTO - SEE LEAK SURVEY MAP
- 83 Wall leak @ PS 349 NO PHOTO - SEE LEAK SURVEY MAP
- 84 Wall leak @ PS 361 NO PHOTO - SEE LEAK SURVEY MAP
- 85 Wall leak @ PS 363 NO PHOTO - SEE LEAK SURVEY MAP
- 86 Wall leak @ PS 369 NO PHOTO - SEE LEAK SURVEY MAP
- 87 Wall leak @ PS 371 NO PHOTO - SEE LEAK SURVEY MAP
- 88 Wall leak @ PS 373 NO PHOTO - SEE LEAK SURVEY MAP

P-3 Subterranean Level Garage

Additional Leak Locations

Defect

89 Wall leak @ PS 375	NO PHOTO - SEE LEAK SURVEY MAP
90 Construction Joint Leak @ PS 375	NO PHOTO - SEE LEAK SURVEY MAP
91 Wall leak @ PS 376	NO PHOTO - SEE LEAK SURVEY MAP
92 Numerous wall leaks @ PS 377	NO PHOTO - SEE LEAK SURVEY MAP
93 Numerous wall leaks @ PS 378	NO PHOTO - SEE LEAK SURVEY MAP
94 Wall leak @ PS 380	NO PHOTO - SEE LEAK SURVEY MAP
95 Multiple wall leaks @ PS 383	NO PHOTO - SEE LEAK SURVEY MAP
96 Wall leak @ PS 384	NO PHOTO - SEE LEAK SURVEY MAP
97 Numerous wall leaks @ PS 385	NO PHOTO - SEE LEAK SURVEY MAP
98 Wall leak @ PS 386	NO PHOTO - SEE LEAK SURVEY MAP
99 Wall leak @ PS 389	NO PHOTO - SEE LEAK SURVEY MAP
100 Wall leak @ PS 390	NO PHOTO - SEE LEAK SURVEY MAP
101 Wall leak in SW Storage room	NO PHOTO - SEE LEAK SURVEY MAP
102 Wall leak @ PS 398	NO PHOTO - SEE LEAK SURVEY MAP
103 Wall leak @ PS 406	NO PHOTO - SEE LEAK SURVEY MAP

P-3 Subterranean Level Garage

Additional Leak Locations

Defect	
104 Construction Joint leak @ PS 408.....	NO PHOTO - SEE LEAK SURVEY MAP
105 Wall leak @ PS 410.....	NO PHOTO - SEE LEAK SURVEY MAP
106 Construction Joint leak @ PS 412.....	NO PHOTO - SEE LEAK SURVEY MAP
107 Wall leak @ PS 414.....	NO PHOTO - SEE LEAK SURVEY MAP
108 Wall leak @ PS 418.....	NO PHOTO - SEE LEAK SURVEY MAP
109 Wall leak @ PS 424.....	NO PHOTO - SEE LEAK SURVEY MAP
110 Wall leak @ PS 430.....	NO PHOTO - SEE LEAK SURVEY MAP
111 Numerous wall leaks @ PS 432.....	NO PHOTO - SEE LEAK SURVEY MAP
112 Wall leak @ PS 436.....	NO PHOTO - SEE LEAK SURVEY MAP
113 Wall leak @ PS 322.....	NO PHOTO - SEE LEAK SURVEY MAP
114 Storage Room Wall leak @ PS 510.....	NO PHOTO - SEE LEAK SURVEY MAP
115 Storage Room Wall leak @ PS 464.....	NO PHOTO - SEE LEAK SURVEY MAP
116 SOG leak @ PS 462.....	NO PHOTO - SEE LEAK SURVEY MAP